

Fertilizer Shed

Herrick Archives Number H 308

A. IDENTIFICATION & LOCATION

1. Name


1.1 Never officially named by Board of Trustees action.

1.2 Alternate names noted:

Fertilizer Building

2. Location

2.1 Located at 3485 Tremont Road. See map below.



For identification of other buildings shown, see Appendix A.

3. General Description

3.1 This was a one-story frame structure west of Building 035. It extended from about 2 feet south of Building H311 to a point about 5' from the south property line.

3.2 The building was constructed in two parts of about equal size. The north half was the original building.

3.3 Dimensions of the building are not known, but photographs and other evidence suggest a building about 18-20' x 60-65'.

B. PLANNING & CONSTRUCTION

This building was constructed by Athletic Department labor. No records have been found, but it is known that the north half was built first. It appears in photograph XI099, presumably taken in 1940. Mr. John S. McCoy on December 15, 1975 stated that the original part of H308 was constructed from lumber left over from

the first addition to the Club House (033). This addition was completed in 1939. It would appear, then, that the first part of H308 was constructed in late 1939 or early 1940.

The south half of H308, according to McCoy, was built from lumber left over from the second addition to the Club House, which was completed in early 1941. It would appear, then, that the south half of H308 was constructed in 1941.

C. DEMOLITION

Demolition of the building was approved by Cabinet on June 16, 1959. It was replaced by Building 175.

D. PHOTOGRAPHS

1. In photoarchives:

Original building - X22610

Addition under construction - X22611

Rear of building (W) - X22612

Front of completed building - X22613; X22615

John H. Herrick
January 20, 1976